


# DigitechSystems Windows Vista32 Touch Screen Driver Install Guide

**Installation Order**


- I. Uncheck User Account Control**
- II. Install DigiTouch5.1.9 Software and Reboot**
- III. Connect Device**
- IV. Install Device Driver**
- V. Installation Complete**
- VI. Calibration**

.....  
.....

- I. Uncheck User Account Control**




Open User Accounts Window in Control Panel.




Uncheck [Use User Account Control (UAC) to help protect your computer] item and reboot.


## II. Install Digitouch Driver Software and Reboot




Execute [setup.exe] in attached DigiTouch5.1.9 and Click Next continue



Choose [USB] item.




Don't change its destination.



Restart your computer.

### III. Connect Device


Connect DigiTouch Device on your system.




System automatically shows above message and select [Ask me again later]

If Device already has been connected on your system, above message don't appears. Then go to step IV. Install Device Driver


#### IV. Install Device Driver



Open Device Manager in Control Panel, Click right button on DigitechSys and Click [Update Driver Software] item.




Click [Browse my computer for driver software].



Click [Browse ... ] Button.




Select the folder : (\\Digitouch5.1.9\_Vista32\\Files)




Click [Install this driver software anyway]

#### V. Installation Complete



Installation Success



Digitouch for usb Driver is loaded on Universal Serial Bus controllers.


## VI. Calibration

Calibration Step calibrates Touch Screen on your system.



Double Click Touch control Manager located at Right Bottom on Desktop





Digitouch Control Manager. Click the third tab 'Calibrate'



Click [Calibrate] button and calibration your system.